


10/547195

1/17

FIG. 1



2/17

FIG. 2




FIG. 3






FIG. 4




3/17

FIG. 5




4/17

FIG. 6




5/17

FIG. 7




6/17

FIG. 8



7/17

FIG. 9



8/17

FIG. 10





FIG. 11



9/17

FIG. 12





FIG. 13

DEFECT ADDRESS	SPARE ADDRESS	OTHER INFO.
ADDRESS aaaa	ADDRESS gggg	
ADDRESS bbbb	ADDRESS kkkk	
ADDRESS cccc	ADDRESS mmmm	
ADDRESS dddd	ADDRESS nnnn	
⋮	⋮	


10/17

FIG. 14



11/17

FIG. 15



10/547195

12/17

FIG. 16






FIG. 17



14/17



15/17

FIG. 19






FIG. 20



16/17

FIG. 21



10/547195

17/17

FIG. 22

